MATERIAL SAFETY DATA SHEET

NEW BALTIMORE, MI 48047 51529 BIRCH STREET RSE INCORPORATED

PHONE: (586) 725-0192 FAX: (586) 725-2225

Activated Carbon Type: RSE A/C - 60 SECTION I **PRODUCT NAME**

SECTION II

HAZARDOUS INGREDIENTS

CAS NUMBER

Carbon (Non-Regulated) Activated Carbon

NAME

7440-44-0

% BY WEIGHT

100

(ACGIH, OSHA and other TLV are not applicable for activated carbon.)

regulations oxygen levels should be taken to ensure ample oxygen availability, observing all local, state and federal vessels and enclosed or confined spaces. Caution: Wet activated carbon removes oxygen from air causing a severe hazard to workers inside carbon denclosed or confined spaces. Before entering such an area, sampling and work procedures for low

SECTION III PHYSICAL DATA

Solubility in Water Vapor Pressure Boiling Point (*F) Z Z Z 무 Packing Density (g/cc) Specific Gravity (water = 1)

1.9-2.2 0.4-0.8 X A

Appearance & Odor Black granular or powder odorless

SECTION IV FIRE & EXPLOSION HAZARD DATA

Ignition Temperature ('C):

350

Flammable Limits Flash Point N N UEL: N/A

Extinguishing Media: Flood with plenty of water or inert gas, such as N2 & CO2

Special Fire Fighting Procedure: None

SECTION V - REACTIVITY

Stability Stable

Hazardous Polymerization Will not occur

Hazardous Decomposition CO may be generated in the event of fire

Condition To Avoid Contact with strong oxidizers, such as ozone, liquid oxygen, chlorine, permanganate and keytone may cause a bed fire.

for further information.) Avoid contact with high concentration of keytone in air or liquid. (Contact RSE

Incompatibility

SECTION VI - HEALTH HAZARD DATA

Carcinogenicity
Acute or Chronic N/A NA Skin : N/A NTP : N/A OSHA : N/A

Ingestion
IARC Monograph:

N N

Inhalation be inhaled Dust may

Signs and Symptoms of Exposure Slight irritation of eyes and nose may result from contact with carbon

fines

Medical Conditions Generally Aggravated By Exposure .. NA

SECTION VII ı **EMERGENCY** ξο **FIRST** AID PROCEDURE

SKin K Ingetion .. N Inhalation .. NA

Eye Flush with plenty of water at least for 15 minutes

Follow-up with physician exam if necessary

SECTION VIII HANDLING Q₀ TORAGE

Protective Clothing Protective Gloves Not Required Rubber Gloves

Eye Protection

Respirator Protection Safety Glasses
A NIOSH approved particulate filter

Ventilation Local & Mechanical exhaust recommended

Storage & Handling Avoid generation of dust and fines during handling

SECTION IX SPILL OR LEAK PROCEDURE

Notify EPA If Product Spills Report in accordance with local, state and federal regulations

Cleaning Procedure Sweep up unused carbon and discard in refuse container or repackage for further

Date:

Prepared By: Maureen Russell